

From: Tyahla.Stephen@epamail.epa.gov
Sent: Wednesday, April 6, 2011 11:45 AM
To: Whelan, Joseph <JWhelan1@wm.com>
Cc: lene.ichinotsubo@doh.hawaii.gov; 'Steven.chang@doh.hawaii.gov'; Miyashiro, Thomas <thomas.miyashiro@doh.hawaii.gov>; alec.wong@doh.hawaii.gov; stuart.yamada@doh.hawaii.gov; Armann.Steve@epamail.epa.gov; Kabei.Arlene@epamail.epa.gov; Vaille.Rich@epamail.epa.gov; Wampler.David@epamail.epa.gov; Helmlinger.Andrew@epamail.epa.gov; Moxley.Bret@epamail.epa.gov
Subject: Re: WGSL, CQA Report Documenting Repairs to the Final Section of Cell E6 Liner
Attach: AOC task due dates-WGSL.xls

Joe,

We have reviewed and approve the subject CQA report (AECOM letter of 4 April 2011, Subject: Liner Damage Assessment, Repair, and Construction Quality Assurance Report for Cell E6 Sideslope, Waimanalo Gulch Sanitary Landfill, Kapolei, HI). EPA concurs that with this approval, Waste Management of Hawaii, Inc. ("WMH") has restored the liner system integrity as required by paragraph 19.f. of our Administrative Order on Consent ("Order") of 25 January 2011.

[One minor error on the report; Figure 1 referred to the Southern Sideslope Liner Area as being part of the "(Current Repair Area)" when in fact AECOM's CQA report of 1 April 2011, as is noted in the text, had included documentation related to repair of this area.]

The attached Order deliverables tracking spreadsheet has been updated to reflect this approval and prior approvals and is provided for your convenience.

Thanks,

Stephen F. Tyahla, P.E., CHMM
Project Manager, RCRA Corrective Action Office
Waste Management Division
U.S. EPA Region IX
75 Hawthorne Street (WST-5)
San Francisco, CA 94105
Ph. 415.972.3466 / Fax 415.947.3533
tyahla.stephen@epa.gov

[This email, including any attachments, may contain non-public, privileged and/or confidential information solely intended to be conveyed to the designated recipient(s). If you receive this email and are not an intended recipient, please delete this email and its attachments immediately. The unauthorized use, dissemination, distribution, or reproduction of this email and its attachments is strictly prohibited by law.]

From: "Whelan, Joseph" <JWhelan1@wm.com>
To: "'Steven.chang@doh.hawaii.gov'" <Steven.chang@doh.hawaii.gov>, "lene.ichinotsubo@doh.hawaii.gov" <lene.ichinotsubo@doh.hawaii.gov>, "Miyashiro, Thomas" <thomas.miyashiro@doh.hawaii.gov>, Stephen Tyahla/R9/USEPA/US@EPA
Date: 04/04/2011 05:54 PM
Subject: WGSL, CQA Report Documenting Repairs to the Final Section of Cell E6 Liner

Greetings all.

Please find the CQA report documenting the liner repairs related to the storm damage located within the northwest portion of Cell E6. This submission documents the final section of the Cell E6 liner repairs. We would appreciate your timely review and approval of this report. Thank you in advance for your assistance with this most important project.

Best regards,

Joe

Joe Whelan

General Manager
Waste Management of Hawaii
808-668-2985, ext. 15 Office
808-668-1366 Fax
808-479-4610 Mobile

Waste Management's landfills provide over 17,000 acres of protected land for wildlife habitats and 15 landfills are certified by the Wildlife Habitat Council.

Waste Management recycles enough paper every year to save 41 million trees. Please recycle any printed emails. [attachment "Ltr Rpt Cell E6 West Slope Repair 040411.pdf" deleted by Stephen Tyahla/R9/USEPA/US]